

VEHICLES CONTAINING MERCURY CONVENIENCE SWITCHES

MAKE / MODEL		MODEL YEAR	SWITCH LOCATION	
AUDI	<i>Audi</i>			
Audi 100		1977-1988	✓ Hood	Trunk
Audi 200		1980-1988	✓ Hood	Trunk
DAIMLERCHRYSLER	<i>Dodge, Chrysler, Jeep, Plymouth, Eagle</i>			
All		1998 and prior	✓ Hood	✓ Trunk
FORD	<i>Ford, Lincoln, Mercury, Mazda, Merkur, Volvo</i>			
Ford Mustang		2000 and prior	✓ Hood	✓ Trunk
Ford Crown Victoria		2000 and prior	✓ Hood	✓ Trunk
Mercury Grand Marquis		2000 and prior	✓ Hood	✓ Trunk
Lincoln Town Car		2000 and prior	✓ Hood	✓ Trunk
Ford, Lincoln, Mercury, and Merkur Cars		1996 and prior	✓ Hood	✓ Trunk
Ford, Lincoln, and Mercury Trucks, SUV's, and Vans		2001 and prior	✓ Hood	Trunk
<i>* Excludes: 1999 and newer model year Ford Ecoline, Ford Windstar, Ford Ranger, and Mercury Villager</i>				
Mazda Navajo		1993-1997	✓ Hood	Trunk
Mazda B-Series Pick-Up		1995-1999	✓ Hood	Trunk
<i>* Ranger/B-Series phased out of mercury switches with 1999 model year.</i>				
Volvo		1991 and prior	✓ Hood	Trunk
<i>* Volvo convenience switches may contain glass mercury capsules. Use care when removing convenience switches from these vehicles.</i>				
GENERAL MOTORS	<i>Chevrolet, GMC, Cadillac, Buick, Oldsmobile, Pontiac, Saturn, Saab</i>			
All Vehicles		1999 and prior	✓ Hood	✓ Trunk
<i>* Excludes: 1999 model year Chevrolet Astro, Chevrolet Silverado, GMC Safari, GMC Sierra</i>				
Cadillac Escalade		2000	✓ Hood	Trunk
Chevrolet Blazer		2000, 2001, 2002	✓ Hood	Trunk
Chevrolet Cavalier		2000, 2001	Hood	✓ Trunk
Chevrolet Corvette		2000	✓ Hood	Trunk
Chevrolet Express		2000, 2001, 2002	✓ Hood	Trunk
Chevrolet S-10 Crew cab		2002	✓ Hood	Trunk
GMC Denali		2000	✓ Hood	Trunk
GMC Envoy		2000, 2001	✓ Hood	Trunk
GMC Jimmy		2000, 2001	✓ Hood	Trunk
GMC Savana		2000, 2001, 2002	✓ Hood	Trunk
GMC Sonoma Crew cab		2002	✓ Hood	Trunk
Luxury G-Van		2001, 2002	✓ Hood	Trunk
Oldsmobile Bravada		2000, 2001, 2002	✓ Hood	Trunk
Pontiac Sunfire		2000, 2001	Hood	✓ Trunk

- **BMW, MITSUBISHI, NISSAN, SUBARU, and VOLKSWAGEN** vehicles DO NOT contain mercury convenience switches.
- Vehicles manufactured 2003 Model Year and beyond DO NOT contain mercury convenience switches.
- Vehicles without trunks including SUVs, station wagons, and hatchbacks DO NOT contain a mercury convenience switch in the "Trunk" or rear of the vehicle.